


[illegible]

FIG.2




FIG.3A




FIG.3B




FIG.3C




FIG.4




FIG.5




FIG.6





FIG.7



A

4

FRASH INITIATED
WHEN A DROPS DOWN

FIG.8




FIG.9




FIG.10




FIG.11




FIG.12




FIG.13




FIG.14

LINE #

01
02
03
04
05
06
07
08
09
10
11
12
13




FIG.15




FIG.16




FIG.17




FIG.18




FIG.19




FIG.20




FIG.21




FIG.22




FIG.23




FIG.24




FIG.25




FIG.26




FIG.27




FIG.28




FIG.29




FIG.30




FIG.31




FIG.32




FIG.33




FIG.34





FIG.35






FIG.36




FIG.37

